		opproved For Release 2001/04/13 : C		
	. 'a.			
COUNTRY Germany (Soviet Zone) TOPIC Cottbus Airfield			2EV4A	
TOPIC GO	TLET	IS ATMITICAL	AMPLICATION THE THE THE THE TOTAL THE	ZONTA  The constitution of the local control of the
CONTRACTOR OF THE PROPERTY OF	ATTENTO ANTIQUE ME	easonamis, siil Ula Alawani, 1995. Nii Stadama kuulkuud rohvalkaajaalan ohkasa vaja muuri. 1929 kuulkuuda kuul 19	TO A LA LETT	25X1A
			TAINED_ 25X1A	regeladition in the reserve of the first had an early selected and desired and place of the edit.
			AND THE PROPERTY OF THE PROPER	8 February 1951
				vienness suprementation to the teach of the second
PAGES	otrako trakon a	2ENCLOSURES (NO. & TYPE)		
REMARKS	Amendakan ru		тутурый, сухиний байн 1 мертинанда устанан н. э. и зарабийн төгөөг төөр төгөө с	
kider solde sovragendrålen ör som klass soorden.	NAME OF THE OWNER, CASE	errometres aguid nul de la Virano, renderes e ences de désait au l'adricir de differentes des rédes des entre elle en de désait de la comme	Harpi inna 1925-menda ing manjangan dan delektron negati sa delaka dalam yang bahasani meningan meningan sa	and the state of t
all the second seco	materia weep			
uz (la 1806) - Michael Marie (La 1806) - Marie (La 1806) - Marie (La 1806) - Marie (La 1806) - Marie (La 1806)	-	rant til præsen at læke ogsåd om 1905 skoket til kall som en anderektinde fleddigt i til til grede som et en stad færet.	Lukerannishe uma kasaranga arang dan dan dan asalah kalan kanarang dan kasarang dan kasarang dan kanarang dan d	- Kappada and Japan II - Amir a rapa and ang
			. •	25X1X
5X1X		by 28 aircraft. Thirteen twin-engine planes were parked at the take-off point, and one group of three planes and three groups of four planes were parked in front of the hangars. (1) There was continual flying, but the number of planes in the air could not be determined. All hangars but one were closed. The aircraft used for flying had single cockpits. The nose of this type plane is pointed alightly more than the nose of the double-cockpit planes. (2) The plane with two cockpits, however, generally appears to be somewhat thinner, and the two angines project beyond the upper edges of the wings. An antenna rod, fitted in front of the cockpit, has antennae leading to the two rudder assemblies.		
2. There was intensive flying all day in a cloudless sky. The fli lasted about 10 minutes. The planes were refueled from tank to After landing, the aircraft taxied to the take-off point on the near the runway. A radio truck with an extended directional lo antenna stood at the take-off point. Another radio with a whip which was placed on the ground near the take-off point was sur by a group of pilots. The radar set was not crected, only its there. (3)				led from tank trucks, -off point on the grass d directional loop adio with a whip antenna ff point was surrounded
	07	The Burger Highway was strictly guarded during flying and blocked when take-offs and landings were made. The field path on the western edge of the landing field was graded and blocked from point 65.6 on the Cottbus-Dahlitz (N 52/A 47) road as far north as point 64.5.		
	L.	Six groups of 15 anti-aircrain point and observed the approximander's scopes. These graquartered in the Funker Kaser toward that saserne. Trucks seen at the entrance to the interpretation of the state	aching aircraft th oups probably below rne because some s	rough six battery nged to the AA unit oldiers were seen walking were
	5.	Five medium-sized containers dump north of the field. The	which arrived rec	ently were seen in the fue
<b>То</b> Н	•	CLASSIFICATION SEPA		t No. /8
		<b>L</b> ,	Decla	ge In Class.   critical
			01 01	anged To: TS SO

SECRET,

2



25X1X

- 6. Between 10:30 and 11:30 a.m. on 16 January, 23 twin-engine, low-wing monoplanes with in-line engines and double rudder 25X1A assemblies were seen in front of the hangars. The observation was made from the southern edge of the field. (1) Ho aircraft were seen in the one open hangar. Three of the parked aircraft which were not covered with tarpaulins were surrounded by approximately 20 men who were probably being instructed. The engines of the planes were started individually.
- 7. The building material previously seen on the southern edge of the landing field was shipped away. Only three small temporary buildings were loft. The runway was completed. The area where the building material was previously stored was being graded by about 40 to 50 men using a power shovel.
- 8. There was no flying on 16 January because of occasional showers and a cloud base of 800 meters. No night lighting facilities were on the new runway.

  Were seen.

25X1C

25X1A

Comments.

(1) The number of aircraft indicates that the occupation of the airfield has not changed compared with the last report of 3 January 1951.

25X1A See \_\_\_\_\_\_\_\_ From the number of planes parked on the landing field it cannot be determined whether one or two bomber regiments are stationed there. According to another source, two bomber regiments are believed to be stationed in Cottbus. Therefore, more aircraft are believed to be parked in the hangars.

- (2) These two aircraft types have been observed at all airfields in the Soviet Zone of Gormany which are occupied by bomber regiments. The employment of the two types, probably two versions of the FE-2, is not known.
- (3) The radar set was removed on 16 December 1950, and to date has not been re-erected.

(4)

25X1C

(5) The arrival of new containers is reported for the first time. It is not known whether these are additional containers or replacements for old ones.



